



I keep most of the larger machines in my shop on mobile bases. Sometimes the machines will move during use, even with the mobile bases locked in the down position. I came up with these "chocks" to keep my machines stable.



These simple wood wedges are inserted under the edge of the mobile base. When not in use, a magnet recessed in one face lets me attach them to the machine leg.